




since 1907

Date : 23.03.2011 - Airjet reed serial number 20112345/2

**AIRFLOW PROTOCOL**


29/03/2011



**Step 1**  
 Received reed from customer the 22.03.2011. Reed airflow inspection before cleaning the reed to check conditions of reed efficiency .

**AIRFLOW PROTOCOL**


29/03/2011



**Step 2**  
 Reed airflow inspection after cleaning the reed by ultrasonic reed cleaning machine.

**AIRFLOW PROTOCOL**

29/03/2011



**Step 3**  
 Reed airflow retuning according to loom type. Pressure was too low. ( Step 2 +-12 Mbar ) Has been corrected to ideal pressure value ( Step 3 +- 18 Mbar)